



A: Placing The Stressmeter Using
The Installation Tool



B: Setting The Stressmeter By
Knocking The Wedge Into The Platen



C: The Installed Stressmeter After
Removal Of The Installation Tool

General Arrangement of Vibrating Wire Stressmeter
05 June 2001 S.Bailey **Not To Scale**

